




# METALLIC

 PU	 2.5 mil	 45° Blade	 MEDIUM pressure	 290°F	 15s	 PEEL: WARM TO COLD
---	--	---	---	---	--	--

**CARRIER: Adhesive & Transparent Polyester**

## APPLIES ON

-  Cotton
-  Polyester
-  Acrylic & Similar Fabrics

## CARE

- Always respect the garment's instructions
- Allow 24 hours after application before washing
- Iron the backside only

## WASH

- Cold hand washing only
- Preferably inside out
- Do NOT bleach
- Do NOT Tumble-dry
- Do NOT Dry-clean

## STORE

- Up to 1 year
- In a dry room (60-85°F)
- Away from sunlight
- In vertical position

## APPLICATION

1. Cut the material in reverse with the recommended blade
2. Weed the excess material
3. Heat press on the garment at 290°F & Protect the polyester carrier with silicone paper 15 sec - medium pressure
4. Peel the carrier off when cold



NOTE: For best results, we recommend performing a TEST prior to starting standard production