




METALLIC

| | | | | | | |
|---|--|---|---|---|--|--|
|  PU |  2.5 mil |  45° Blade |  MEDIUM pressure |  290°F |  15s |  PEEL: WARM TO COLD |
|---|--|---|---|---|--|--|

CARRIER: Adhesive & Transparent Polyester

APPLIES ON

-  Cotton
-  Polyester
-  Acrylic & Similar Fabrics

CARE

- Always respect the garment's instructions
- Allow 24 hours after application before washing
- Iron the backside only

WASH

- Cold hand washing only
- Preferably inside out
- Do NOT bleach
- Do NOT Tumble-dry
- Do NOT Dry-clean

STORE

- Up to 1 year
- In a dry room (60-85°F)
- Away from sunlight
- In vertical position

APPLICATION

1. Cut the material in reverse with the recommended blade
2. Weed the excess material
3. Heat press on the garment at 290°F & Protect the polyester carrier with silicone paper 15 sec - medium pressure
4. Peel the carrier off when cold



NOTE: For best results, we recommend performing a TEST prior to starting standard production