

# FIRSTMARK

OEKO-TEX®  
CONFIDENCE IN TEXTILES  
STANDARD 100 

Class 1

\*Class 2

 PVC	 4-5 mil	 45° Blade	 MEDIUM pressure	 300°F	 10-15s	 PEEL: WARM TO COLD
--	--	---	---	---	---	--

**CARRIER: Adhesive & Transparent Polyester**

## APPLIES ON

-  Cotton
-  Polyester
-  Acrylic & Similar Fabrics

## CARE

- Always respect the garment's instructions
- Allow 24 hours after application before washing
- Iron the backside only

## WASH

- Max 140° F
- Preferably inside out
- Do NOT bleach
- Tumble-dry
- Do NOT Dry-clean

## STORE

- Up to 1 year
- In a dry room (60-85°F)
- Away from sunlight
- In vertical position

## APPLICATION

1. Cut the material in reverse with the recommended blade
2. Weed the excess material
3. Heat press on the garment at 300°F & Protect the polyester carrier with silicone paper 10 - 15 sec - medium pressure
4. Peel the carrier off when cold

 **Chemica US**  
Transfer your imagination

NOTE: For best results, we recommend performing a TEST prior to starting standard production